



ASBESTOS INVENTORY CONTROL

BUILDING SERVICES DIVISION

BUILDING NAME: ELDON ROSS POOL	INSPECTION DATE: August 15, 2006
BUILDING CODE: PI-06	INSPECTED BY: Karl Bauch
BUILDING ADDRESS: 1887 PACIFIC AVE	Year Built: 1982

LEGEND- Application Type: **PW**-Pipe Wrap **SO**-Spray On **HB**-Hardboard **EN**-Encapsulated **R**-Removed **PL**-Plaster
TI-Tank Insulation **C**-Ceiling **F**-Flooring **DW**-Ductwork **LF** – Loose Fill
 Condition: **G**-Good **NR**-Need Repair
 Inspection Frequency: **B**-Per 6 Months **Y**-Yearly **2Y**-Two Years **5Y**-Five Years

Asbestos Location	Description	Application Type	Estimated %	General Condition	Inspection Frequency	Area Tested	
						Yes	No
MAIN FLOOR LEVEL							
Women's Locker Room	Pipe Elbows	PW		G	2 Y		No
Men's Locker Room	Pipe Elbows	PW		G	2 Y		No
Mechanical Room	Pipe Elbows	PW		G	2 Y		No
Equipment Room	Pipe Elbows	PW		G	2 Y		No
Pool Deck South West Corner	Pipe Elbows	PW		G	2 Y		No
East Mechanical Room	Pipe Elbows	PW		G	2 Y		No
Boiler Room / East Pool Deck	Pipe Elbows	PW		G	2 Y		No
	Tank Insulation	TI		G	2 Y		No
	Ductwork	DW		G	2 Y		No
Activity Room / East Pool Deck	Pipe Elbows	PW		G	2 Y		No
Supervisors Office	Pipe Elbows	PW		G	2 Y		No
Staff Change Room / Lunch Room	Pipe Elbows	PW		G	2 Y		No
Main Floor Ceiling	Ceiling tile in front lobby	C	0 %	G	2 Y	Yes	
Exterior Parging	Hardboard around perimeter of building	HB		G	2 Y		No
Boiler Room	Hardboard asbestos attached to flashing	HB		R	2 Y		No
Block walls of old portion of building (Pool tank room & mechanical rooms)	Contain vermiculite insulation which may contain asbestos.	LF		G	2Y		No