



Photo 1 – Existing Building to be demolished



Photo 2 – Existing Asbestos wallboard to be removed (main floor).



Photo 3 – Existing Electrical to be removed (main floor)



Photo 4 – Existing Pump motors to be removed (main floor)



Photo 5 – Existing Piping to be removed (lower level)



Photo 6 – Existing Piping to be removed (lower level)



Photo 7 – Existing Pumps and Divider Walls to be Removed (Wetwell)



Photo 8 – Existing Submersibles to be salvaged (wet well)



Photo 9 – Existing Slide gate to be removed



Photo 10 – Existing Slide gate to be removed



Photo 11 – Deep pond and intake pipe (April 10, 2007)



Photo 12 – Intake Pipe (April 10, 2007)



Photo 13 – Intake Pipe – Typical Wall Crack



Photo 14 – Intake Pipe – Typical Ceiling Crack and Spalling.



Photo 15 – Intake Pipe – Typical Wall Crack and Spalling



Photo 16 – Intake Pipe – Typical Wall Hairline Crack