

APPENDIX C

ADDITIONAL SITE PHOTOS OF OUTFALL SITES REQUIRING PRIVATE PROPERTY AUTHORIZATION



Photo 1: 2782 Assiniboine Avenue – Looking east along shoreline



Photo 2: 2782 Assiniboine Avenue – Looking west along shoreline/backyard of 2782 Assiniboine Ave.



Photo 3: 2782 Assiniboine Avenue – Looking south at upstream manhole within driveway



Photo 4: 2782 Assiniboine Avenue – Looking southwest within front yard of 2782 Assiniboine Ave.



Photo 5: 2782 Assiniboine Avenue – Looking south at intermediate manhole location (manhole is along fenceline)



Photo 6: Looking south from front of 2788 Assiniboine Ave. (along proposed access route)



Photo 1: Wellington Crescent – Looking east along shoreline



Photo 2: Wellington Crescent – Looking north along existing feedermain alignment (City owned ROW along 925 Wellington Cr.)



Photo 3: Wellington Crescent – Looking north at existing feedermain overhead crossing



Photo 4: Wellington Crescent – Looking south along existing feedermain alignment (City owned ROW along 925 Wellington Cr.)



Photo 5: Wellington Crescent – Looking north along 925 Wellington Cr. driveway



Photo 6: Wellington Crescent – Looking north along 925 Wellington Cr. driveway



Photo 7: Wellington Crescent – Looking northwest at back of 925 Wellington Cr. property



Photo 8: Wellington Crescent – Looking northwest at back of 925 Wellington Cr. property



Photo 1: 50 Eastwood Drive – Looking northwest along pipe alignment



Photo 2: 50 Eastwood Drive – Looking northwest along pipe alignment between 34 Eastwood Dr. and 50 Eastwood Dr.



Photo 3: 50 Eastwood Drive – Looking southeast along pipe alignment between 34 Eastwood Dr. and 50 Eastwood Dr.



Photo 4: 50 Eastwood Drive – Looking northwest along pipe alignment near existing flood dike



Photo 5: 50 Eastwood Drive – Looking west along top of bank



Photo 6: Looking northeast along top of bank



Photo 1: 300 Dunkirk Drive – Looking north at pipe outlet/shoreline



Photo 2: 300 Dunkirk Drive – Looking southwest at pipe outlet/shoreline



Photo 3: 300 Dunkirk Drive – Looking south at pipe outlet



Photo 4: 300 Dunkirk Drive – Looking southeast from 300 Dunkirk Drive backyard



Photo 5: 300 Dunkirk Drive – Looking southeast along pipe alignment



Photo 6: 300 Dunkirk Drive - Looking east along driveway access



Photo 1: 1 Hart Avenue – Looking west from mid-bank



Photo 2: 1 Hart Avenue – Looking east towards pumping station



Photo 3: 1 Hart Avenue – Looking south along shoreline



Photo 4: 1 Hart Avenue – Looking north along shoreline



Photo 5: 1 Hart Avenue – Looking south at pipe outlet



Photo 6: 1 Hart Avenue – Looking west towards pumping station from Glenwood Crescent



Photo 1: 3087 Vialoux Drive – Looking north along pipe alignment towards 3087 Vialoux Dr.



Photo 2: 3087 Vialoux Drive – Looking east to entrance of existing asphalt path from Vialoux Dr.



Photo 3: 3087 Vialoux Drive – Looking west from asphalt path back towards Vialoux Dr.



Photo 4: 3087 Vialoux Drive – Looking south from mid-bank area along property line between existing park space and 3079 Vialoux Dr.



Photo 5: 3087 Vialoux Drive – Looking west along shoreline



Photo 6: 3087 Vialoux Drive – Looking east along shoreline



Photo 1: 2464 Assiniboine Crescent – Looking south from Assiniboine Crescent



Photo 2: 2464 Assiniboine Crescent – Looking south from mid-bank along pipe alignment



Photo 3: 2464 Assiniboine Crescent – Looking north at existing chamber



Photo 4: 2464 Assiniboine Crescent – Looking south from existing chamber