



**Water and Waste Department • Service des eaux et des déchets**

*Environmental Standards Division • Division des Normes Environnementales*

July 27, 2017

Our File No: 040-17-08-29-00

Manitoba Sustainable Development  
Environmental Compliance and Enforcement Branch  
1007 Century Street  
Winnipeg, MB R3H 04W

040-17-08-15-00

040-17-08-35-00

Attention: Mr. Don Labossiere, Regional Director

**RE: JUNE 2017 MONITORING REPORTS FOR THE WEST END WATER  
POLLUTION CONTROL CENTRE LICENCE NO. 2669 E RR, THE NORTH END  
WATER POLLUTION CONTROL CENTRE LICENCE NO. 2684 RRR AND THE  
SOUTH END WATER POLLUTION CONTROL CENTRE LICENCE NO. 2716 RR**

---

The June 2017 Monitoring Reports for Licence No. 2669 E RR issued for the City of Winnipeg West End Water Pollution Control Centre (WEWPCC), Licence No. 2684 RRR issued for the City of Winnipeg North End Water Pollution Control Centre (NEWPCC) and Licence No. 2716 RR issued for the City of Winnipeg South End Water Pollution Control Centre (SEWPCC) are attached. This information is provided under compulsion of law in accordance with the requirements under the Environment Act Licences #2669 E RR, #2684 RRR and #2716 RR.

Please note the following respecting the report for Licence #2669 E RR:

1. The TSS results met the licence limit in June.
2. There were no cBOD5 results on June 3, 7, and 20 due to QC failures and no cBOD5 result on June 26 due to a technician error; the cBOD5 results met the licence limit in June.
3. The ammonia results met the licence limit in June.
4. The total phosphorus and total nitrogen thirty-day rolling averages met the licence limits in June.
5. The monthly geometric means for fecal coliform and *E. coli* met the licence limits in June.

Please note the following respecting the report for Licence #2684 RRR:

1. The TSS result exceeded the licence limit on three days in June due to intermittent high flows and by-pass events.
2. There were no BOD5 and cBOD5 results on June 3, 7, and 20 due to QC failures, no BOD5 or cBOD5 results on June 12 and no cBOD5 result on June 26 due to technician errors. The BOD5 result exceeded the licence limit on four days in June due to intermittent high flows and by-pass events. The total daily flow exceeded 380 MLD on June 14, therefore in accordance with the licence, the BOD value for this day is not considered to be an exceedence.
3. The monthly geometric means for fecal coliform and *E. coli* met the licence limits in June.



Please note the following respecting the report for Licence #2716 RR:

1. The TSS results met the licence limit in June.
2. There were no BOD5 and cBOD5 results on June 3, 7, and 20 due to QC failures and no cBOD5 result on June 26 due to a technician error; the cBOD5 results met the licence limit in June.
3. There were no results for ammonia and ortho-phosphorus on June 28 due to a technician error.
4. The monthly geometric mean for *E. coli* met the licence limit in June.

Please let me know of any concerns or questions respecting this submission. I can be reached by telephone at 204-986-8359 or by email at [rgrosselle@winnipeg.ca](mailto:rgrosselle@winnipeg.ca).

Yours sincerely,

*Original signed by R. Grosselle:*

R. Grosselle  
Manager of Environmental Standards

NC

Enclosures

cc: M. L. Geer CPA, CA (e-mail)  
C. Carroll, P. Eng (e-mail)