



Water and Waste Department • Service des eaux et des déchets

Environmental Standards Division • Division des Normes Environnementales

June 29, 2017

Our File No: 040-17-08-29-00

Manitoba Sustainable Development
Environmental Compliance and Enforcement Branch
1007 Century Street
Winnipeg, MB R3H 04W

040-17-08-15-00

040-17-08-35-00

Attention: Mr. Don Labossiere, Regional Director

**RE: MAY 2017 MONITORING REPORTS FOR THE WEST END WATER
POLLUTION CONTROL CENTRE LICENCE NO. 2669 E RR, THE NORTH END
WATER POLLUTION CONTROL CENTRE LICENCE NO. 2684 RRR AND THE
SOUTH END WATER POLLUTION CONTROL CENTRE LICENCE NO. 2716 RR**

The May 2017 Monitoring Reports for Licence No. 2669 E RR issued for the City of Winnipeg West End Water Pollution Control Centre (WEWPCC), Licence No. 2684 RRR issued for the City of Winnipeg North End Water Pollution Control Centre (NEWPCC) and Licence No. 2716 RR issued for the City of Winnipeg South End Water Pollution Control Centre (SEWPCC) are attached. This information is provided under compulsion of law in accordance with the requirements under the Environment Act Licences #2669 E RR, #2684 RRR and #2716 RR.

Please note the following respecting the report for Licence #2669 E RR:

1. The TSS results met the licence limit in May.
2. There was no cBOD5 result on May 26 due to a QC failure; the cBOD5 results met the licence limit in May.
3. The ammonia results met the licence limit in May.
4. The total phosphorus and total nitrogen thirty-day rolling averages met the licence limits in May.
5. There was no result for *E. coli* on May 7 due to a contract lab error; the monthly geometric means for fecal coliform and *E. coli* met the licence limits in May.

Please note the following respecting the report for Licence #2684 RRR:

1. There was no 24-hour composite sample on May 3 and 11 due to sampler malfunctions.
2. The TSS result exceeded the licence limit on one day in May due to intermittent high flows and bypass events.
3. There were no BOD5 and cBOD5 results on May 26 due to a QC failure; the BOD5 result exceeded the licence limit on one day in May due to intermittent high flows and bypass events.
4. There was no result for *E. coli* on May 7 due to a contract lab error; the monthly geometric means for fecal coliform and *E. coli* met the licence limits in May.



Please note the following respecting the report for Licence #2716 RR:

1. There was no 24-hour composite sample on May 12, 13, 14, and 18 due to a malfunction in the automatic control system for the final effluent sampler.
2. The TSS results met the licence limit in May.
3. There were no BOD5 and cBOD5 results on May 26 due to a QC failure; the cBOD5 results met the licence limit in May.
4. There was no result for *E. coli* on May 7 due to a contract lab error; the monthly geometric mean for *E. coli* met the licence limit in May.

Please let me know of any concerns or questions respecting this submission. I may be reached by telephone at 204-986-8359 or by email at rgrosselle@winnipeg.ca.

Yours sincerely,

Original signed by R. Grosselle:

R. Grosselle
Manager of Environmental Standards

NC

Enclosures

cc: M. L. Geer CPA, CA (e-mail)
C. Carroll, P. Eng (e-mail)