

NOTES:

- EXISTING CONCRETE ROADWAY WITH ASPHALT OVERLAY.
- CURB AND SIDEWALK REPLACEMENT TO BE MINIMAL..
- CONCRETE ROADWAY REPAIRS TO BE MINIMIZED. USE TECHNIQUE OF FULL DEPTH CONCRETE REPAIRS.
- TIE IN PAVING AT SIDE STREETS AND APPROACHES TO BE MINIMIZED.
- APPROXIMATE SLAB AND JOINTS TO BE RENEWED, 548 m2
- APPROXIMATE PARTIAL DEPTH REPAIRS, 55 m2
- APPROXIMATE SIDEWALK TO BE RENEWED, 230 m2
- APPROXIMATE CURB TO BE RENEWED, 264 m
- AVERAGE ASPHALT THICKNESS TO BE PLACED, 60 mm
- L = 1045 m W = 14.0 ± m A = 14630 m2
- TOTAL AREA INCLUDING TURN LANES AND MEDIAN OPENINGS = 15779 m2

CONSTRUCTION NOTES:

- CONTRACTOR TOOK PRECAUTIONARY STEPS TO AVOID DAMAGE FROM CONSTRUCTION ACTIVITIES TO EXISTING BOULEVARDS AND TREES WITHIN THE LIMITS OF CONSTRUCTION.
- 2. LOCATION OF EXISTING SERVICES CONFIRMED IN THE FIELD BY THE CONTRACTOR.
- 3. TIE-INS VERIFIED IN THE FIELD BY THE CONTRACT ADMINISTRATOR.
- 4. JOINT, SLAB, CURB AND SIDEWALK REPAIRS MARKED OUT IN THE FIELD BY THE CONTRACT ADMINISTRATOR.
- 5. CONTRACTOR RESPONSIBLE FOR ALL BARRICADES AND SIGNAGE EXCEPT REGULATORY SIGNS (eg. NO LEFT TURNS) SUPPLIED BY TRAFFIC SERVICES BRANCH.
- DO NOT MILL EXPOSED CONCRETE UNLESS
 OTHERWISE DIRECTED BY THE CONTRACT
 ADMINISTRATOR.

