

APPENDIX C
PHOTOGRAPHS



Photo 0-1 NEWPCC- Site Photo Taken in 2006

Clarifier 1



Photo 1-1 Effluent Weir



Photo 1-2 Scum Trough & Discharge Box



Photo 1-3A 150 mm CI Pipe-Remove



Photo 1-3B 150 mm CI Pipe-Remove



Photo 1-3C 150 mm Pipe-Removal



Photo 1-3D 150 mm Pipe-Removal

Clarifier 2



Photo 2-1 Scum Trough Discharge Box



Photo 2-2 Effluent Weir & Scum Baffle



Photo 2-3 Clarifier Walkway Enclosure



Photo 2-4 Clarifier Walkway Enclosure Connection

Clarifier 3



Photo 3-1 Concrete Clarifier Influent Pipe/Base



Photo 3-2 Top of Concrete Clarifier Influent Pipe/Base



Photo 3-3 Effluent Weir & Scum Baffle



Photo 3-4 Scum Baffle



Photo 3-5 Scum Baffle



Photo 3-6 Effluent Weir & Launder



Photo 3-7 Walkway Enclosure Hinged Scum Blade Access Panels



Photo 3-8 Clarifier Drained



Photo 3-9 Clarifier Drained



Photo 3-10 Clarifier Drained



Photo 3-11 Clarifier Drained



Photo 3-12 Clarifier Drained



Photo 3-13 Clarifier Drained



Photo 3-14 Clarifier Walkway & Enclosure



Photo 3-15 Enclosure Hinged Scum Blade Access Panels



Photo 3-16 Walkway Enclosure Hinged Scum Blade Access Panels



Photo 3-17 Walkway Enclosure Hinged Scum Blade Access Panels



Photo 3-18 Walkway Enclosure



Photo 4-1 Clarifier Control Building – Location for Proposed Screw Conveyor



**Photo 4-2 Clarifier Control Building – Center Ring –
Location for Proposed Screw Conveyor**



Photo 4-3 Clarifier Control Building – Location for Scum Disposal Bin