ISSUED FOR TENDER

99% CLIENT REVIEW

90% CLIENT REVIEW

NO. REVISIONS

LOCATION OF UNDERGROUND STRUCTURES AS SHOWN ARE BASED ON THE BEST

LOCATION ARE EXACT. CONFIRMATION OF

EXISTENCE AND EXACT LOCATION OF ALL

SERVICES MUST BE OBTAINED FROM THE

INDIVIDUAL UTITLITIES BEFORE PROCEEDING WITH CONSTRUCTION.

INFORMATION AVAILABLE. BUT NO GUARANTEE IS GIVEN THAT ALL EXISTING UTILITIES ARE SHOWN OR THAT THE GIVEN CHECKED BY

APPROVED

DATE

RELEASED FOR

CONSTRUCTION

DRAWN

SCALE

19.06.20 KK

19.06.14 KK

DATE BY

19.05.16

KK

indicated

Issue Date

JDI

04/03/19

D'IGNAZIO

CONSULTANT PROJECT NUMBER

60602875

TACHE BOOSTER PUMPING STATION

MAIN BUILDING

**RE-ROOFING** 

ARCHITECTURAL

DETAILS SHEET 2 OF 2

CITY DRAWING NUMBER

1-0660M-B0003-002

CONSULTANT DRAWING NUMBER

A104

oF 6

AECOM REVIEW DRFT CHK