



Figure 1 – Existing Sidewalk Repair on North Side of River from Launch Wye Assembly Installation, looking North.



Figure 2 – Existing Launch Wye Installed on North Side of River.



Figure 3 – Excavation location on South Side of River from Launch Wye Assembly Installation, looking North.



Figure 4 – Existing Launch Wye and Valve Installed on South Side of River.



Figure 5 – Steel Water Main Sample Cut during Launch Wye Installation in 2015.



Figure 6 – Cast Iron Water Main Sample Cut during Launch Wye Installation in 2015.



Figure 7 – Access Gate Located in Shaarey Zedek Synagogue Parking Lot, looking Southeast.



Figure 8 – East Bridge Structure and Access Location to South Side of River, looking Northwest from Access Gate.



Figure 9 – General Site Layout between Bridge Structures on South Side of Crossing, looking North.



Figure 10 – General Site Layout on North Side of Crossing, looking East.