

**APPENDIX E**  
**WELLINGTON CRESCENT OUTFALL**  
**INTERNAL PIPE PHOTOS**




Photo 1: Approx. Sta. 1+90 looking d/s



Photo 2: Approx. Sta. 1+96.1 looking d/s




Photo 3: Approx. Sta. 1+97.3 looking d/s



Photo 4: Approx. Sta. 1+98.9 looking d/s



Photo 5: Approx. Sta. 2+00.1 looking d/s



Photo 6: Approx. Sta. 2+02 looking d/s